MET Sydney Pty Ltd
134 Carnarvon Street
Silverwater NSW 2128

www.metrecycling.com.au
Phone **1300 638 123**
EPL No: 20948

Dust Monitoring Results - October 2026

Air Quality Monitoring Data (Daily 24-Hour Average Concentrations)

Date	PM_{10} Monitoring Pt A	$PM_{2.5}$ Monitoring Pt A	PM_{10} Monitoring Pt B	$PM_{2.5}$ Monitoring Pt B
1/10/2026	8.25	3.71	21.86	6.27
2/10/2026	16.29	8.75	16.89	8.35
3/10/2026	8.29	5.29	6.63	4.07
4/10/2026	-	-	-	-
5/10/2026	-	-	6.53	3.74
6/10/2026	-	-	8.00	3.71
7/10/2026	13.65	4.60	12.64	4.91
8/10/2026	22.81	8.41	15.49	7.23
9/10/2026	12.21	4.32	11.07	4.03
10/10/2026	9.53	3.88	13.56	4.89
11/10/2026	8.89	4.55	11.72	5.30
12/10/2026	14.85	8.08	15.72	7.79
13/10/2026	12.99	5.01	31.63	9.09
14/10/2026	12.20	7.31	10.18	5.63
15/10/2026	11.73	5.43	11.01	4.79
16/10/2026	6.75	3.11	7.87	3.13
17/10/2026	7.37	3.45	8.53	3.42
18/10/2026	5.70	2.51	7.31	2.96
19/10/2026	5.48	2.95	6.54	2.81
20/10/2026	8.25	3.60	9.12	3.71
21/10/2026	8.35	3.59	8.34	3.45
22/10/2026	8.93	4.41	8.03	3.95
23/10/2026	11.95	7.32	11.53	6.29
24/10/2026	7.46	4.20	7.79	4.04

MET Sydney Pty Ltd
134 Carnarvon Street
Silverwater NSW 2128

www.metrecycling.com.au
Phone **1300 638 123**
EPL No: 20948

25/10/2026	7.96	4.39	9.57	5.43
26/10/2026	3.70	1.80	6.56	2.58
27/10/2026	10.15	5.02	11.57	4.93
28/10/2026	11.45	5.30	12.58	5.28
29/10/2026	27.51	4.39	9.79	3.16
30/10/2026	12.37	3.67	12.65	4.02

Missing particulate monitoring data were recorded on 4, 5 and 6 October 2026. No daily average results were available on 4 October 2026. On 5 and 6 October 2026, Dust Gauge 1 (ET28D0001) PM_{10} and $PM_{2.5}$ data were unavailable due to a site power interruption. Monitoring was restored following a circuit breaker reset and overall data capture remained greater than 97%, such that the missing data are not considered to materially affect interpretation of monitoring results.

Date	Missing Data	Justification / Action Taken
4 October 2026	No daily average result recorded for DG1 or DG2 PM_{10} and $PM_{2.5}$	No specific outage was recorded in the monitoring records. The date was a Sunday, and no daily average result was generated. The formal missing data assessment did not identify an instrument fault on this date.
5 October 2026	DG1 PM_{10} and $PM_{2.5}$	Site power interruption resulted in loss of monitoring data from Dust Gauge 1. The monitoring system was restored following a circuit breaker reset and normal data acquisition resumed.
6 October 2026	DG1 PM_{10} and $PM_{2.5}$	Continuation of the power interruption issue affecting Dust Gauge 1. Monitoring resumed following circuit breaker reset. Normal operation was restored after the outage.